

## Center Drawer

### Tools Required

- Drill
- Phillips Head Bit
- Tape Measure or Ruler
- Pencil

### Package Contents

- Center drawer with two slides
- 4 Screws

### Installation

1. Locate center drawer by setting back  $\frac{1}{4}$ " from front edge of worksurface at the desired location. (Figure A).
2. Hold center drawer in place and mark the locations for the slide screws on the underside of the worksurface.
3. Attach drawer in marked locations using screws provided.

**Note:** Center drawer cannot be used under a 24"D worksurface when using a modesty panel.

Figure A

