

Innsbruck/Osterley Park

Conference Table Bases

Tools Required

- Adjustable Wrench
or Socket Set

Package Contents

- 3 Adjustable Glides
- 6 Washers
- 6 Bolts

Caution: It is recommended that more than one person be used to assemble and move conference tables.

Installation

1. Place the assembled worksurface upside down on a smooth, solid surface.
2. Remove the shipping pad from the bottom of each pedestal base.
3. Position the pedestal bases on their circular mounting pads. Turn each so that one prong is towards the center of the table. Align the six (6) mounting holes in each pedestal base with the holes in each mounting pad. Use six (6) bolts and washers to attach each pedestal base to the mounting pads. (Figure A).
4. Insert three (3) adjustable glides into each pedestal base. (Figure B).
5. Carefully turn assembled unit upright. (Figure C).

Figure A




Figure B




Figure C

