

Array[®]

Wire Manager Attachment

Tools Required

- Variable Speed Drill with Torque Option
- #2 Phillips Bit

Package Contents

- 1 30" Cable Manager
- 10 #8 x 3/4" Panhead Phillips Wood Screws

Installation

1. Turn table upside down and place on solid surface.
2. Attach cable manager 2 1/4" from edge of table using screws provided.

Note: When using two managers, allow for closure of folding legs.

