

Footprint® Worksurface & Support

Mobile Table Leg

Tools Required

- Power Drill
- Phillips Bit

Package Contents

- 1 or 4 Table Legs
- #8 x 1" Trusshead Phillips Flakeboard Screws (6 per leg)

Installation

Note: Crescent table shown for illustration.

1. Place table top face down on a clean, solid surface or floor; (protect top from marks and scratches).
2. Position table leg mounting plates over pre-drilled holes and align. Attach leg to top using (6) #8 x 1" screws (supplied). Repeat for other three legs. (Figure A).
3. **Adjustable Leg:**

To raise table, lift weight off of table leg and depress bullet catches simultaneously. Let each leg fall into desired position and allow bullet catches to "snap" into nearest locking position.

To lower table, depress bullet catches simultaneously and gently press down on table to reach desired height. Release catches allowing them to "snap" into nearest locking position.

Repeat procedure with other legs making sure all legs are in identical locking positions/same height. (Figure B).

Figure A




Figure B

